

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

# BioForest Sweep




FIG 1

CANISTER


BFR 0010

REV 0

Drawn By : KCB  
Date : 03/09/08


Gen Tol:  $\pm 0.002$   
All edges to be broken ( $\sim 0.002$  R)

Black Box Solutions Inc.  
P.O. Box 742, Waukenaushene, Ontario, Canada, L0K 2C0  
Phone (705) 794-2318 / Fax (705) 538-0492




1B

1C



<b>BFR 0001</b> <b>INJECTOR</b>	Gen Tol: $\pm 0.010$ All edges to be broken ( $\sim 0.002$ R)	Drawn By: KCB Date: 03/09/09	REV: 0
<b>Black Box Solutions Inc.</b>	Phone (705) 794-2318 / Fax (705) 538-0492 P.O. Box 742, Waubesa, Ontario, Canada, L0K 2C0		







Fig. 3



30  
FIG 4

Fig. 5.

A.

B.








Fig. 6

A



B



C




Fig. 7

